## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES COMMUNITY ENVIRONMENTAL SERVICES

133293

## LAND DISPOSAL INSPECTION REPORT

Disposal Facility Facility Add							
Buckman Landtill		Rd. # / Honey book					
Cou	nty Ches lec Municipalit	V Her	ey b	7 c /s	7	CUP.	
<sup>5</sup> rop		Proprietor's Address					
Mr. Ernest Backman		Same					
	•						cc
	Type Record	ł	6				1
	Identification			lumber 100812			
	Inspection D	ate	08		OA	YR */~2	8-13
	Reinspection	n Date	09	[2	0	72	14-19
			·	CMPL 1	N-CMPL 2	_ N/A 3	
1.	ALL WEATHER ACCESS ROADS TO THE SITE FOR TWO-WAY TRAFFIC OR SEP- FOR ONE-WAY TRAFFIC NEGOTIABLE BY LOADED COLLECTION VEHICLES.	ARATE RO	ADS	1			20
2.	TELEPHONE OR RADIO COMMUNICATIONS ACCESSIBLE TO THE SITE.			1			21
3.	ADEQUATE EQUIPMENT FOR MINIMIZING FIRE HAZARDS AVAILABLE.			1			22
4.	ALL BUILDINGS AND EQUIPMENT PROVIDED WITH FUNCTIONAL FIRE EXTIN	GUISHERS	<b>s.</b>				23
5.	ACCESS LIMITED TO THOSE TIMES WHEN AN ATTENDANT IS ON DUTY.			1			24
	A. HOURS OF OPERATION PROMINENTLY POSTED.			1			25
	B. SUITABLE BARRIER AND FENCING BLOCKS ACCESS TO THE SITE WHEN A ATTENDANT IS NOT ON DUTY.	N					26
<b>6</b> ,	APPROVED OPERATIONAL SAFETY PROGRAM FOLLOWED AT SITE.				1		27
7.	ADEQUATE SANITARY FACILITIES PROVIDED FOR THE EMPLOYEES.			1			28
<b>в</b> .	MAINTENANCE OF DAILY OPERATIONAL RECORDS.			1			29
9.	FOLLOWING OPERATIONAL PLAN ITEMS FOLLOWED AT SITE:						
	A. AREA TO BE FILLED				[2]		30
	SCHEDULE OF FILLING				.3		31
-	C. SITE PREPARATION				2		32
	D. SOURCE AND TYPES OF COVER MATERIAL				7		33
	E. SOURCE AND TYPES OF SUB-BASE				2		10007,5

YES NO

Z

ARE HA

ARE HAZARDOUS WASTES RECEIVED AT THE SITE (If Yes, List Types on Next Page.)

## **CORRECTIVE PRIORITY PROGRAM:**

The following items are not in compliance with Pa. Dept. of Environmental Resources standards

699- Phase of the Solid waste module has been submitted & is being reviewed.

17- Daily cover in some places is less than

19- Final cover is still required on some spots along the back of the 1:1%.

22 9 26 - Several junk vehicles of scrap metal still must be removed from the site.

28- Slopes of the reas of the lift are in excess of 15%

John Z. (Region I Soil Scientist) and Ralph Z. (Region I Gologist) investigated the site.

Bruce Beitle

OPERATOR (Signature)

THIS PAGE LEFT INTENTIONALLY BLANK

TANGER OF THE SECOND SE

Harris Communication (Section 2) (1997) (199

responsibility of the state of

Off CAMA